


Exhibit X

to Development Agreement

SH Loop 337 Owner & Third Party Improvements



PAPE-DAWSON
ENGINEERS

555 EAST RAMSEY | SAN ANTONIO, TEXAS 78216 | PHONE: 210.375.9000
FAX: 210.375.9010
TEXAS BOARD OF PROFESSIONAL ENGINEERS, FIRM REGISTRATION # 470

EXHIBIT X
SH LOOP 337 OWNER AND
THIRD PARTY IMPROVEMENTS



INTERIM REVIEW ONLY
Document incomplete. Not intended for
permit, bidding or construction.
Engineers: GILMER D. GASTON
P.E. Serial No: 80472
Date: 2/15/2013

JOB NO. 7620-00

DATE FEB 2013

CHECKED GG DRAWN DM

SHEET 1 OF 3



INTERIM REVIEW ONLY
Document incomplete. Not intended for
permit, bidding or construction.
Engineers: GILMER D. GASTON
P.E. Serial No: 80472
Date: 2/15/2013


EXHIBIT X

*SH LOOP 337 OWNER AND
THIRD PARTY IMPROVEMENTS*

**PAPE-DAWSON
ENGINEERS**

5555 EAST RAMSEY | SAN ANTONIO, TEXAS 78216 | PHONE: 210.375.9000
FAX: 210.375.9010
TEXAS BOARD OF PROFESSIONAL ENGINEERS, FIRM REGISTRATION # 470

Design File name: D:\76\20\09\exhibits\EX130215SuperArterial*ROW*X3.dgn
Plotted on: 2/15/2013



MATCHLINE STA 240+00

ROADWAY B

BMB RANCH HOLDINGS LTD

BMB RANCH HOLDINGS LTD

INDEPENDENCE DRIVE

S.H. 46

N. WALNUT AVE.

OAK RUN

PRELIMINARY
SUBJECT TO CHANGE

PRELIMINARY
SUBJECT TO CHANGE

LEGEND

- EXISTING ROADWAY
- THIRD PARTY SH LOOP 337 IMPROVEMENTS
- OWNER SH LOOP 337 IMPROVEMENTS

SCALE: 1" = 400'

0' 400'

INTERIM REVIEW ONLY
Document incomplete. Not intended for permit, bidding or construction.
Engineer: GILMER D. GASTON
P.E. Serial No: 80472
Date: 2/15/2013

EXHIBIT X

**SH LOOP 337 OWNER AND
THIRD PART IMPROVEMENTS**

**PAPE-DAWSON
ENGINEERS**

555 EAST RAMSEY | SAN ANTONIO, TEXAS 78216 | PHONE: 210.375.9000 FAX: 210.375.9010
TEXAS BOARD OF PROFESSIONAL ENGINEERS, FIRM REGISTRATION # 470

JOB NO. 7620-00
DATE FEB 2013
CHECKED GG DRAWN DM
SHEET 3 OF 3